

Алматы (7273)495-231
Ангарск (3955)42-70-56
Архангельск (8182)63-90-72
Астрахань (8512)99-46-04
Барнаул (3852)73-04-42
Белгород (4735)40-23-142
Благовещенск (4162)35-142-07
Брянск (4232)59-03-52
Владивосток (423)249-42-31
Владикавказ (8672)42-90-42
Владимир (4935) 49-43-18
Волгоград (844)278-03-42
Вологда (8172)26-41-59
Воронеж (473)204-51-73
Екатеринбург (343)384-55-142

Ижевск (3412)26-03-58
Иваново (4932)77-34-06
Иркутск (395)279-98-46
Казань (843)206-01-42
Калининград (4012)72-03-81
Калуга (4242)92-23-67
Кемерово (3842)65-04-62
Киров (8332)68-02-04
Коломна (4966)23-41-49
Кострома (4942)77-07-42
Краснодар (861)203-40-90
Красноярск (391)204-63-61
Курск (4712)77-13-04
Курган (4352)50-90-47
Липецк (4742)52-20-81

Киргизия (996)312-96-26-47

Магнитогорск (4219)55-03-13
Москва (495)268-04-70
Мурманск (8152)59-142-93
Набережные Челны (8552)20-53-41
Нижний Новгород (831)429-08-12
Новокузнецк (3843)20-46-81
Ноябрьск (3496)41-32-12
Новосибирск (383)357-86-73
Ноябрьск (3496)41-32-12
Омск (3812)21-46-40
Орел (4262)44-53-42
Оренбург (4232)37-68-04
Пенза (8412)35-31-16
Петрозаводск (8142)55-98-37
Псков (8112)59-10-37

Россия (495)268-04-70

Пермь (342)205-81-47
Ростов-на-Дону (863)308-18-15
Рязань (4912)46-61-142
Самара (846)206-03-16
Саранск (8342)35-96-24
Санкт-Петербург (812)309-46-40
Саратов (845)249-38-78
Севастополь (8692)35-31-93
Симферополь (3652)67-13-56
Смоленск (4212)29-41-42
Сочи (862)242-72-31
Ставрополь (8652)20-65-13
Сыктывкар (8212)42-95-17
Сургут (3462)77-98-42
Тамбов (4752)50-40-97

Казахстан (772)734-952-31

Тверь (4352)63-31-42
Тольятти (8435)63-91-07
Томск (3835)98-41-53
Тула (4272)33-79-87
Тюмень (3452)66-21-18
Улан-Удэ (3012)59-97-51
Ульяновск (8435)24-23-59
Уфа (347)359-42-12
Хабаровск (4212)92-98-04
Чебоксары (8435)42-53-07
Челябинск (421)202-03-61
Череповец (8202)49-02-142
Чита (3035)38-34-83
Якутск (4112)23-90-97
Ярославль (4422)69-52-93

<https://topas.nt-rt.ru> || tac@nt-rt.ru

Шкаф кондиционирования TDC 584. Технические характеристики



testcabinet for filter discharge TDC 584

The harmonization of international testing standard ISO 16890-4 requires neutralization of tested filter element by Iso-propyl-alchole (IPA) treatment. Therefore a suitable test cabinet for filter discharging is needed. The solution proposed in ISO 16890-4, chapter 7 requires a large amount of hazardous substance with at least about 1 l of liquid IPA, whereas particularly the handling of the trays filled with liquid IPA is risky. Furthermore large quantities of IPA saturated air enter the laboratory after opening the cabinet, which is a sanitary as well as a safety-related problem. It also requires an air extraction of the complete laboratory area.

Due to these problems TOPAS decided to develop a new cabinet for the filter conditioning according to ISO 16890-4.

Special Advantages

- Fast and constant saturation of the air with IPA
- Integrated suction and flushing of the chamber (Exhaust air guidance required)
- Low use of IPA of max. 1l per conditioning (several filters possible)
- Certification of security level by accredited certification bodies

Applications

- Conditioning of air filters according to ISO 16890-4 (for followed testing of the mechanical separation behaviour with the General Air Filter Test System Topas ALF 114)
- Electrostatic neutralization of bag- and cartridge filters, filter bags and flat media

Technical Data (abstract)

Cabinet volume for filter element(s):	610 mm x 610 mm x 950 mm (WxDxH)
Auxiliary process time of filter conditioning	
Saturation	15 min
Flushing	30 min
Dimensions	1200 mm x 1200 mm x 1900 mm
Weight	250 kg